

Electrostatic Bender Optics

R. Baartman

TRIUMF

Abstract: The relativistically-correct Hamiltonian and transfer matrix of electrostatic benders is derived. This is the general case where the bender electrodes have curvature in the non-bend direction.

4004 Wesbrook Mall, Vancouver, B.C. Canada V6T 2A3 Tel: 604 222-1047 Fax: 604 222-1074 www.triumf.ca

1 Introduction

A common approach, used especially by those accustomed to only magnetic elements, is to let the third momentum be $\Delta p/p$. This is not the simplest approach, since when electric fields are included, it is not conserved. This means that when a particle enters the electrostatic element off-axis, it must receive a "kick" to get into the potential field. This kicks p, but to first order leaves E unchanged. For an electrostatic bend of radius A, this kick is $\Delta p/p = \pm x/A$; the upper sign is for entry, the lower for exit.

A better approach is therefore to let the third momentum be E. Since the fields are static, E is conserved; no kicks are required.

For independent variable s, on a reference trajectory curving in the xs-plane with curvature h = 1/A, the Hamiltonian $H = -p_s$ is well-known, and I will not derive it here:

$$H = -(1+hx)\sqrt{\left(\frac{E-q\Phi}{c}\right)^2 - m^2c^2 - p_x^2 - p_y^2}$$
(1)

We write $E = E_0 + \Delta E$, and note that the large quantity under the square root sign is

$$p_0^2 = E_0^2 / c^2 - m^2 c^2 = (\gamma^2 - 1)m^2 c^2 = (\beta \gamma m c)^2,$$
(2)

the square of the reference momentum.

$$H = -(1+hx)p_0\sqrt{1 + \frac{2E_0(\Delta E - q\Phi)}{p_0^2c^2} + \left(\frac{\Delta E - q\Phi}{p_0c}\right)^2 - \frac{p_x^2}{p_0^2} - \frac{p_y^2}{p_0^2}}$$
(3)

Let us transform so that the third coordinate is not time, but a relative distance deviation w.r.t. the reference particle: i.e. from $(t, -\Delta E)$ to (τ, p_{τ}) where $\tau \equiv s - \beta ct$, $p_{\tau} = \Delta E/(\beta c)$. The generating function is

$$F(t, p_{\tau}) = (s - \beta ct)p_{\tau} \tag{4}$$

then the new Hamiltonian is $K = H + \partial F / \partial s = H + p_{\tau}$

$$K = p_{\tau} - (1 + hx)p_0 \sqrt{1 + 2\left(\frac{p_{\tau}}{p_0} - \frac{q\Phi}{\beta c p_0}\right) + \beta^2 \left(\frac{p_{\tau}}{p_0} - \frac{q\Phi}{\beta c p_0}\right)^2 - \frac{p_x^2}{p_0^2} - \frac{p_y^2}{p_0^2}}$$
(5)

This cleans up considerably if we scale all momenta and the Hamiltonian by p_0 : $P_x = p_x/p_0$, $P_y = p_y/p_0$, $P_\tau = p_\tau/p_0$, $\tilde{K} = K/p_0$, and introduce the scaled potential $V = \frac{q\Phi}{\beta c p_0}$:

$$\tilde{K} = P_{\tau} - (1 + hx)\sqrt{1 + 2(P_{\tau} - V) + \beta^2(P_{\tau} - V)^2 - P_x^2 - P_y^2}$$
(6)

This also makes the momenta accord with the more usual definitions, since, as we will see, $P_x = x'$, $P_y = y'$, and outside the electric field, $P_\tau = \Delta p/p$.

2 Potential

To second order, the potential V is given by

$$V = hx - h(h+k)\frac{x^2}{2} + hk\frac{y^2}{2},$$
(7)

where h = 1/A and $k = 1/A_y$ is the curvature in the non-bend direction. This can be derived by solving Laplace's equation in a curvilinear coordinate system that has different curvatures in the xs- and xy-planes, then transforming back to the chosen dynamical system, which is curved only in the xs-plane¹. We can, however, show the above potential to be correct for the two simplest cases – cylindrical and spherical.

Example: Cylindrical bend

Here k = 0, the potential is $V = -\log(A/r) = \log(1 + hx)$, since the distance r to the bend centre is x + A. Expanding, we find

$$V = hx - \frac{h^2 x^2}{2} + \frac{h^3 x^3}{3} - \dots$$
(8)

This agrees with eqn. 7 for k = 0.

Example: Spherical bend

Here k = h, the potential is $V = 1 - A/r = 1 - 1/\sqrt{1 + 2hx + h^2x^2 + h^2y^2}$, since the distance r to the bend centre is $\sqrt{(x+A)^2 + y^2}$. Expanding, we find

$$V = hx - h^2 x^2 + \frac{h^2 y^2}{2} + h^3 x^3 - \frac{3h^3 x y^2}{2} + \cdots$$
(9)

This agrees with eqn. 7 for k = h.

In any case, the first term, needed to ensure that the reference trajectory is x = 0, yields the required electric field on the reference orbit:

$$\mathcal{E} = -\frac{\partial \Phi}{\partial x} = -\frac{\beta c p_0}{q} \left. \frac{\partial V}{\partial x} \right|_{x=0} = \frac{\beta^2}{A} \frac{E_0}{q}.$$
 (10)

In the non-relativistic limit, the electric field is twice the beam kinetic energy divided by charge and bend radius: $q\mathcal{E} = mv^2/A$.

3 Hamiltonian and Transfer Matrix

The first order terms in the resulting Hamiltonian all cancel, so when expanded to second order it is

$$\tilde{K} = \frac{P_x^2}{2} + \frac{P_y^2}{2} + \frac{P_\tau^2}{2\gamma^2} - \frac{2-\beta^2}{A}xP_\tau + \frac{\xi^2}{2A^2}x^2 + \frac{\eta^2}{2A^2}y^2$$
(11)

The parameters ξ and η are introduced as they parameterize the x and y focusing strengths: $\xi^2 + \eta^2 = 2 - \beta^2, \eta^2 = k/h = A/A_y, A_y$ being the curvature radius in the non-bend direction. In the non-relativistic limit, for a cylindrical bend, $\xi = \sqrt{2}, \eta = 0$; for a spherical bend, $\xi = \eta = 1$.

Page c

、

The transfer matrix is easily derived from this Hamiltonian \tilde{K} :

$$\begin{pmatrix} \cos \xi \theta & \frac{A}{\xi} \sin \xi \theta & 0 & 0 & 0 & \frac{2-\beta^2}{\xi^2} A(1-\cos \xi \theta) \\ -\frac{\xi}{A} \sin \xi \theta & \cos \xi \theta & 0 & 0 & 0 & \frac{2-\beta^2}{\xi^2} \sin \xi \theta \\ 0 & 0 & \cos \eta \theta & \frac{A}{\eta} \sin \eta \theta & 0 & 0 \\ 0 & 0 & -\frac{\eta}{A} \sin \eta \theta & \cos \eta \theta & 0 & 0 \\ -\frac{2-\beta^2}{\xi} \sin \xi \theta & -\frac{2-\beta^2}{\xi^2} A(1-\cos \xi \theta) & 0 & 0 & 1 & A\theta \left[\frac{1}{\gamma^2} - \left(\frac{2-\beta^2}{\xi} \right)^2 \left(1 - \frac{\sin \xi \theta}{\xi \theta} \right) \right] \\ 0 & 0 & 0 & 0 & 0 & 1 \end{pmatrix}$$

$$(12)$$

Interestingly, in the extreme relativistic limit ($\beta = 1$), this is identical to the matrix for a magnetic bend with field index.

References

[1] R. Baartman: End Effects of Beam Transport Elements, Talk at Snowmass 2001, http://lin12.triumf.ca/text/Talks/2001Snowmass/FF.ps